

Item 9. Emergency Repair to CCTV cabling at Hordle Pavilion

Current Situation:

New CCTV cameras were installed earlier this year at Hordle Pavilion. Two cameras have stopped working and engineers have discovered that the cabling (original when the previous system was installed) has been chewed by rodents.

A new armoured cable to prevent further damage by rodents has been recommended and can be run along the existing ducting and install rodent proof junction boxes. The company who installed the new cameras has quoted the following to undertake the repairs:

2 x 4 by 4 Wiska Boxes
Armoured Cat 5e Cable

Please note 2 engineers will be required for the works.

Subtotal	£995.00
VAT @ 20%	£199.00
Total	£1194.00

The quote was reported to the Finance, Audit and Compliance Committee, who approved the quote to undertake the emergency work.

Recommendation:

That the above quote is ratified.